RESOLUTION NUMBER 2019-03

RESOLUTION REVIEWING COMPLIANCE MAINTENANCE REPORT

WHEREAS, the Village of North Hudson informs the Department of Natural Resources that the following actions were taken by the Village of North Hudson Board of Trustees.

THEREFORE, the Village Board of Trustees has reviewed the Compliance Maintenance Annual Report, which is attached to this Resolution.

BE IT RESOLVED, that the Compliance Maintenance Annual Report be forwarded by the Village Treasurer to the Department of Natural Resources.

Dated this 4th day of June, 2019.

_____

Signed: Stan Wekkin, Village President

_____

Attest: Melissa Luedke, Village Clerk

Village of North Hudson, WI

Compliance Maintenance Annual Report

North Hudson Village

Last Updated: 5/23/2019 Reporting For: **2018**

Financial Management

1. Provider of Financial Information

Name: Nathan Troester

Telephone: (715)386-9807 (XXX) XXX-XXXX

E-Mail Address (optional): ntroester@northhudsonvillage.org

2. Treatment Works Operating Revenues

2.1 Are User Charges or other revenues sufficient to cover O&M expenses for your wastewater treatment plant AND/OR collection system ?

- ● Yes (0 points) ☐☐
- ○ No (40 points)

If No, please explain:

2.2 When was the User Charge System or other revenue source(s) last reviewed and/or revised?

Year: 2018

- ● 0-2 years ago (0 points) ☐☐
- ○ 3 or more years ago (20 points)☐☐
- ○ N/A (private facility)

2.3 Did you have a special account (e.g., CWFP required segregated Replacement Fund, etc.) or financial resources available for repairing or replacing equipment for your wastewater treatment plant and/or collection system?

- ● Yes (0 points)
- ○ No (40 points)

0

REPLACEMENT FUNDS [PUBLIC MUNICIPAL FACILITIES SHALL COMPLETE QUESTION 3]

3. Equipment Replacement Funds

3.1 When was the Equipment Replacement Fund last reviewed and/or revised?

Year: 2018

- ● 1-2 years ago (0 points)☐☐
- ○ 3 or more years ago (20 points)☐☐
- ○ N/A

If N/A, please explain:

3.2 Equipment Replacement Fund Activity

3.2.1 Ending Balance Reported on Last Year's CMAR		$ 51,140.26
3.2.2 Adjustments - if necessary (e.g. earned interest, audit correction, withdrawal of excess funds, increase making up previous shortfall, etc.)	-	$ 2,351.28
3.2.3 Adjusted January 1st Beginning Balance		$ 48,788.98
3.2.4 Additions to Fund (e.g. portion of User Fee, earned interest, etc.)	+	$ 87,417.73

Compliance Maintenance Annual Report

North Hudson Village

Last Updated: 5/23/2019 Reporting For: **2018**

3.2.5 Subtractions from Fund (e.g., equipment replacement, major repairs - use description box 3.2.6.1 below*) - $ 82,517.17

3.2.6 Ending Balance as of December 31st for CMAR Reporting Year $ 53,689.54

All Sources: This ending balance should include all Equipment Replacement Funds whether held in a bank account(s), certificate(s) of deposit, etc.

3.2.6.1 Indicate adjustments, equipment purchases, and/or major repairs from 3.2.5 above.

There were 2 Lift Stations that Needed to be repaired and replaced in 2018.

3.3 What amount should be in your Replacement Fund? $ 28,000.00

0

Please note: If you had a CWFP loan, this amount was originally based on the Financial Assistance Agreement (FAA) and should be regularly updated as needed. Further calculation instructions and an example can be found by clicking the SectionInstructions link under Info header in the left-side menu.

3.3.1 Is the December 31 Ending Balance in your Replacement Fund above, (#3.2.6) equal to, or greater than the amount that should be in it (#3.3)?

- ● Yes
- ○ No

If No, please explain.

4. Future Planning

4.1 During the next ten years, will you be involved in formal planning for upgrading, rehabilitating, or new construction of your treatment facility or collection system?

- ● Yes - If Yes, please provide major project information, if not already listed below.☐☐
- ○ No

Project #	Project Description	Estimated Cost	Approximate Construction Year
1	East Bank Lift Station Rehab Project	45000	2020

5. Financial Management General Comments

None

ENERGY EFFICIENCY AND USE

6. Collection System

6.1 Energy Usage

6.1.1 Enter the monthly energy usage from the different energy sources:

COLLECTION SYSTEM PUMPAGE: Total Power Consumed

Number of Municipally Owned Pump/Lift Stations: 4

Compliance Maintenance Annual Report

North Hudson Village

Last Updated: 5/23/2019 Reporting For: **2018**

	Electricity Consumed (kWh)	Natural Gas Consumed (therms)
January	880	0
February	900	0
March	680	0
April	577	0
May	497	0
June	470	0
July	495	0
August	444	0
September	471	0
October	498	0
November	622	0
December	1,086	0
Total	**7,620**	**0**
Average	**635**	**0**

6.1.2 Comments:

N/A

6.2 Energy Related Processes and Equipment

6.2.1 Indicate equipment and practices utilized at your pump/lift stations (Check all that apply):

- ☒ Comminution or Screening
- ☐ Extended Shaft Pumps
- ☒ Flow Metering and Recording
- ☐ Pneumatic Pumping
- ☐ SCADA System
- ☐ Self-Priming Pumps
- ☒ Submersible Pumps
- ☐ Variable Speed Drives
- ☐ Other:

6.2.2 Comments:

None

6.3 Has an Energy Study been performed for your pump/lift stations?

- ● No
- ○ Yes

Year:

By Whom:

Describe and Comment:

Compliance Maintenance Annual Report

North Hudson Village

Last Updated: 5/23/2019 Reporting For: **2018**

6.4 Future Energy Related Equipment

6.4.1 What energy efficient equipment or practices do you have planned for the future for your pump/lift stations?

Research on Installation of Solar Panels.

Total Points Generated	0
Score (100 - Total Points Generated)	100
Section Grade	**A**

Compliance Maintenance Annual Report

North Hudson Village

Last Updated: 5/23/2019 Reporting For: **2018**

Sanitary Sewer Collection Systems

1. Capacity, Management, Operation, and Maintenance (CMOM) Program

1.1 Do you have a CMOM program that is being implemented?

- ● Yes
- ○ No

If No, explain:

1.2 Do you have a CMOM program that contains all the applicable components and items according to Wisc. Adm Code NR 210.23 (4)?

- ● Yes
- ○ No (30 points)
- ○ N/A

If No or N/A, explain:

1.3 Does your CMOM program contain the following components and items? (check the components and items that apply)

☒ Goals [NR 210.23 (4)(a)]

Describe the major goals you had for your collection system last year:

Pump out and power wash wet wells of all lift stations in Village.

Did you accomplish them?

- ● Yes
- ○ No

If No, explain:

☒ Organization [NR 210.23 (4) (b)]☐☐

Does this chapter of your CMOM include:

- ☒ Organizational structure and positions (eg. organizational chart and position descriptions)
- ☒ Internal and external lines of communication responsibilities
- ☒ Person(s) responsible for reporting overflow events to the department and the public

☒ Legal Authority [NR 210.23 (4) (c)]

What is the legally binding document that regulates the use of your sewer system?

Sewer Use Ordinance

If you have a Sewer Use Ordinance or other similar document, when was it last reviewed and revised? (MM/DD/YYYY) 2000-05-01

Does your sewer use ordinance or other legally binding document address the following:

- ☒ Private property inflow and infiltration
- ☒ New sewer and building sewer design, construction, installation, testing and inspection
- ☐ Rehabilitated sewer and lift station installation, testing and inspection
- ☐ Sewage flows satellite system and large private users are monitored and controlled, as necessary
- ☒ Fat, oil and grease control
- ☒ Enforcement procedures for sewer use non-compliance

☒ Operation and Maintenance [NR 210.23 (4) (d)]

Does your operation and maintenance program and equipment include the following:

- ☒ Equipment and replacement part inventories
- ☒ Up-to-date sewer system map
- ☒ A management system (computer database and/or file system) for collection system information for O&M activities, investigation and rehabilitation

Compliance Maintenance Annual Report

North Hudson Village

Last Updated: 5/23/2019 Reporting For: **2018**

☒ A description of routine operation and maintenance activities (see question 2 below)
☒ Capacity assessment program
☒ Basement back assessment and correction
☒ Regular O&M training

☐ Design and Performance Provisions [NR 210.23 (4) (e)]☐☐

What standards and procedures are established for the design, construction, and inspection of the sewer collection system, including building sewers and interceptor sewers on private property?

☐ State Plumbing Code, DNR NR 110 Standards and/or local Municipal Code Requirements
☐ Construction, Inspection, and Testing
☐ Others:

☒ Overflow Emergency Response Plan [NR 210.23 (4) (f)]☐☐

Does your emergency response capability include:

☒ Responsible personnel communication procedures
☒ Response order, timing and clean-up
☒ Public notification protocols
☒ Training
☒ Emergency operation protocols and implementation procedures

☐ Annual Self-Auditing of your CMOM Program [NR 210.23 (5)]☐☐

☐ Special Studies Last Year (check only those that apply):

☐ Infiltration/Inflow (I/I) Analysis
☐ Sewer System Evaluation Survey (SSES)
☐ Sewer Evaluation and Capacity Managment Plan (SECAP)
☐ Lift Station Evaluation Report
☐ Others:

0

2. Operation and Maintenance

2.1 Did your sanitary sewer collection system maintenance program include the following maintenance activities? Complete all that apply and indicate the amount maintained.

Cleaning	100	% of system/year
Root removal	100	% of system/year
Flow monitoring	100	% of system/year
Smoke testing	0	% of system/year
Sewer line televising	50	% of system/year
Manhole inspections	50	% of system/year
Lift station O&M	4	# per L.S./year
Manhole rehabilitation	10	% of manholes rehabbed
Mainline rehabilitation	0	% of sewer lines rehabbed
Private sewer inspections	0	% of system/year
Private sewer I/I removal	0	% of private services

Compliance Maintenance Annual Report

North Hudson Village

Last Updated: 5/23/2019 Reporting For: **2018**

River or water crossings: 0 % of pipe crossings evaluated or maintained

Please include additional comments about your sanitary sewer collection system below:

3. Performance Indicators

3.1 Provide the following collection system and flow information for the past year.

33.57	Total actual amount of precipitation last year in inches
30	Annual average precipitation (for your location)
17.1	Miles of sanitary sewer
4	Number of lift stations
0	Number of lift station failures
0	Number of sewer pipe failures
0	Number of basement backup occurrences
0	Number of complaints
	Average daily flow in MGD (if available)
	Peak monthly flow in MGD (if available)
	Peak hourly flow in MGD (if available)

3.2 Performance ratios for the past year:

0.00	Lift station failures (failures/year)
0.00	Sewer pipe failures (pipe failures/sewer mile/yr)
0.00	Sanitary sewer overflows (number/sewer mile/yr)
0.00	Basement backups (number/sewer mile)
0.00	Complaints (number/sewer mile)
	Peaking factor ratio (Peak Monthly:Annual Daily Avg)
	Peaking factor ratio (Peak Hourly:Annual Daily Avg)

4. Overflows

LIST OF SANITARY SEWER (SSO) AND TREATMENT FACILITY (TFO) OFERFLOWS REPORTED **

	Date	Location	Cause	Estimated Volume (MG)
None reported				

** If there were any SSOs or TFOs that are not listed above, please contact the DNR and stop work on this section until corrected.

5. Infiltration / Inflow (I/I)

5.1 Was infiltration/inflow (I/I) significant in your community last year?

- ○ Yes
- ● No

If Yes, please describe:

5.2 Has infiltration/inflow and resultant high flows affected performance or created problems in your collection system, lift stations, or treatment plant at any time in the past year?

- ○ Yes
- ● No

If Yes, please describe:

Compliance Maintenance Annual Report

North Hudson Village

Last Updated: 5/23/2019 Reporting For: **2018**

5.3 Explain any infiltration/inflow (I/I) changes this year from previous years:

NA

5.4 What is being done to address infiltration/inflow in your collection system?

NA

Total Points Generated	0
Score (100 - Total Points Generated)	100
Section Grade	**A**

Compliance Maintenance Annual Report

North Hudson Village

Last Updated: 5/23/2019 Reporting For: **2018**

Grading Summary

WPDES No: 0047341

SECTIONS	LETTER GRADE	GRADE POINTS	WEIGHTING FACTORS	SECTION POINTS
Financial	A	4	1	4
Collection	A	4	3	12
TOTALS			**4**	**16**
GRADE POINT AVERAGE (GPA) = 4.00				

Notes:
A = Voluntary Range (Response Optional)
B = Voluntary Range (Response Optional)
C = Recommendation Range (Response Required)
D = Action Range (Response Required)
F = Action Range (Response Required)

Compliance Maintenance Annual Report

North Hudson Village

Last Updated: 5/23/2019 Reporting For: **2018**

Resolution or Owner's Statement

Name of Governing Body or Owner: Village of North Hudson

Date of Resolution or Action Taken: 2019-06-04

Resolution Number: 2019-03

Date of Submittal:

ACTIONS SET FORTH BY THE GOVERNING BODY OR OWNER RELATING TO SPECIFIC CMAR SECTIONS (Optional for grade A or B. Required for grade C, D, or F):

Financial Management: Grade = A

A

Collection Systems: Grade = A
(Regardless of grade, response required for Collection Systems if SSOs were reported)

A

ACTIONS SET FORTH BY THE GOVERNING BODY OR OWNER RELATING TO THE OVERALL GRADE POINT AVERAGE AND ANY GENERAL COMMENTS
(Optional for G.P.A. greater than or equal to 3.00, required for G.P.A. less than 3.00)
G.P.A. = 4.00